TO BE PROCESSED, BY SPECIAL DESIGNEES ONLY Approved For Release 2002/06/13 : CtA-RDP69B0004\R001600010047-0 25X1A 25X1A T O P S E C R T T 261800Z CITE 0076 INFO IMMEDIATE IMMEDIATE 25X1A 25X1A OXCART 25X1A BX 6747 FLASH REPORT AFTER PROCESSING TYPE 1 D.

E. THE FILM ARRIVED IN GOOD PHYSICAL CONDITION. MISSION HAD GOOD
RESOLUTION, NORMAL EXPOSURE, METERING AND OPERATIONAL DATA RECORDING.
FILM WAS SLIGHTLY HIGH IN APPARENT CONTRAST. MINUS DENSITY LINES
WERE NOTED IN ALL FWD FRAMES 5/8 INCHES FROM LEADING EDGE AND
1 1/4 INCHES FROM TRAILING EDGE. A MINUS DENSITY LINE WAS OBSERVED
IN ALL AFT FRAMES 2 1/4 INCHES FROM THE LEADING EDGE. AN EXTREMELY
FINE PLUS DENSITY SCRATCH OCCURRED 5/8 INCHES FROM LEADING EDGE,
INTERMITTENTLY THROUGHOUT THE MISSION. DATA CHAMBERS WERE COCKED
APPROXIMATELY 5 DEGREES TO LEFT OF PERPENDICULAR IN ALL FRAMES,
CAUSING SOME DATA CHAMBERS TO ENTER IMAGERY. EXCESSIVE BLURRING
CAUSED BY CAGING WAS NOTED FROM FRAMES 1247 TO 1265.

TOPSECRET

BT

Approved For Release 2002/06/13 : CIA-RDP69B00041R0016000100470

27. ANGO 95 31/2

HDFXBKEAX MR

UDYGVONL311!":":782E1A062ALA876 YKA313

OO RUEIWW RUEIWF

DE RUALYK 154 @270515

ZNY XXXXX

0 2705 00Z ZFF1

BT

XXXXX

TO BE PROCESSED BY SPECIAL DESIGNERS ONLY

			Ź				
						25X1A	
TOPSFCR	270	5007 JAN	8 CITE	0079			
MALDIATE		ineo irreo	· <b></b>		25X1A	25X1A	
A SYESAT		_				25X1A	

- B. FILM EVALUATION REPORT
- C. TYPE IC
- D. FULTRON DEREXMX578/47 SEC/86 DEGREES F
- E. 2.81/2.67 T.26 T.27
- 7. 3488/484-2-19-7
- (1) GOOD Approved For Release 2002/06/13 : CIA-RDP69B00041R001600010047-0
  - (2) GOOD

- (5) OPERATIONAL Approved For Release 2002/06/13 : CIA-RDP69B00041R001600010047-0
- H. O.N. DISPOSITION TO E.K. THREE DUPE POS TO NATIONAL CUSTOMERS.

  SEVEN DUPE POS AND 1 DUPE NEG TO THEATRE CUSTOMERS. NORMAL STAPTUP

  AND SHUT DOWN. MINUS DENSITY LINES WERE NOTED IN ALL FWD FRAMES

  3" FROM LEADING EDGE AND 1 1/4" FROM TRAILING EDGE. A MINUS

  DENSITY LINE WAS OBSERVED IN ALL AFT FRAMES 2 1/4" FROM THE LEADING

25X1A

PAGE 2 0079 TO P SECRET

EDGE AND EXTREMELY FINE PLUS DENSITY SCRATCH OCCURED 5/8" FROM

LEADING EDGG INTERMITTENLY THROUGHOUT THE MISSION. DATA CHAMBERS

WERE COCKED APPROXIMATELY 5 DEGREES TO LEFT OF PERPENDICULAR IN

ALL FRAM'S, CAUSING SOME DATA CHAMEBRS TO ENTER IMAGE AREA.

EXCESSIVE BLURRING CAUSED BY CAGEING APPAPENT IN FRAMES 1247

TO 1265. FRAMES 1 THRU 4 TITLING IN IMAGE AREA. FRAMES

327 AND 328 HANDLING MARKS. FRAME 485 PINHOLES. MINUS DENSITY

LINE 3/4" FROM TRAILING EDGE. OVERLAP IN FRAMES 1001 THRU 1036.

DATA PECORDING CHAMBER DOUBLE EXPOSED ON 1023 AND 1024. 1355

THRU 1364 SHUTDOWN FACTORY SPLICE FRAME 1240. FRAME 1241 TRACKED

OFF ON TRAILING EDGE.

TOPSECRET

BT

010047-0

NNNNZCZC86	9A542		· · · · · · · · · · · · · · · · · · ·		<b>6</b>	M 13 / Oz
374/290303	Z ZFF-1 ZP	0		25X1A		
ET	of task (Permanagh)					- 5 0 1 8 <b>0</b> 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	] 25×1A					
TOPSE	P B T 29	8258Z JAN	68 CITE	750	1	25X1A 25X1A
IMMEDIATE [						25X1A
REF A. BX	2441					25X1A
MSN B)	(6847 WAS	AN EXCELLE	NT MISSI	ON EXCEP	T FOR A VER	
FEW FRAMES	THAT HAD	PPROX 5 I	NCH OVER	LAP. TH	IS COULD	
POSSIBLY BE	CAUSED BY	AIRCRAFT	TURNS,	TURN ON/	OFF OR POSS	IBLY
AN OCCASION	AL METERIN	G PROBLEM	. UNTIL	IT IS D	ETERMINED	
EXACTLY WHY	THIS OVER	LAP OCCUR	RED REQU	EST THE	OTHER TWO	
TYPE I CAME	RAS BE USE	D OR, IF	NECESSAR	Y, IC BE	USED IN	
BACK-UP ACF	т.					

Duc PU UNSTANT 2.7

TOPSECRET

Approved For Release 2002/06/13: CIA-RDP69B00041R001600010047-0

BT

	<i>M</i>	· 13 4/2		
0		. :		1
ZZZCZCØ68JEDT T		* * * * * * * * * * * * * * * * * * *		
FTP130/011928Z ZP0	25X	1A 🦿		
ВТ			28239	
XXXXX		p.esp.	And the second	
	25X1A	* Control of the Cont		14.14.22
			08.41	
TOPSECRET 011920Z FEB	S 68 CITE	2882.	25X1A	
				e de la companya de
PRIORITY INFO		g q magazantik de	おうない 神経の神経の関連 影響	一般 発達 ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・
		7	25X1A	
A. BX 6847		Sak	25X1A	
B. INS FILM CORRELATION REPORT			25X1A	
C. INS 010			20/(1/(	
D. 1. SATISFACTORY				
2. SAT ISFACT ORY				
3. SAT ISFACTORY				
4. SATISFACTORY				
5. SATISFACTORY				
6. SATISFACTORY				
7. SATISFACTORY				
8. SATISFACTORY				
9. SAT ISFACTORY				
TOT FILM CLICK SHOWS A PIAS	OF MINUS_47 TO	9 SECONDS	. 성독한 사람 취임	Fr. Hilly
THROUGHOUT THE MISSION.				
E. SATISFACTORY CORRELATION HA	S BEEN ACHIEVED	ON THIS MISS	ION.	
* ^ 0 0 0 0 0 0 0 0 0 0				,

BT

Next 8 Page(s) In Document Exempt